



## NHTSA Safety Recall 15V-625

**TO:** Winnebago Industries, Inc. Dealers

**SUBJECT:** Campaign #135 – High-Pressure LP Hose

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owners may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. As you will see in reading the enclosed copy of the letter which is being sent to owners, the owners are being instructed to contact Winnebago Industries, Inc. if you do not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

### **REASON FOR THIS RECALL**

Winnebago Industries, Inc. has decided that a defect which relates to motor vehicle safety exists on certain 2013 through 2016 model year Winnebago Touring Coach™ Era®, Winnebago Trend™, and Itasca Viva!™ motorhomes.

These motorhomes were manufactured June 28, 2012 through August 6, 2015. With time, the high-pressure LP hose may harden and develop a leak at the crimp fitting. Should a leak develop, a potential for a fire or explosion can result.

### **OWNER NOTIFICATION**

Owners will be notified of this campaign on their vehicles by Winnebago Industries, Inc. For all units in your inventory, the notification will be mailed to you. **DO NOT DELIVER TO A CUSTOMER ANY SUBJECT UNIT UNTIL CORRECTIVE ACTION HAS BEEN TAKEN.** Enclosed is a list of vehicles shipped to you.

### **DEALER CAMPAIGN RESPONSIBILITY**

Dealers are to service all vehicles subject to this campaign at no charge to owners regardless of mileage, age of vehicle, or ownership from this time forward.

Whenever a vehicle subject to this campaign is taken into new or used vehicle inventory or it is in your dealership for service in the future, you should take the steps necessary to be sure the campaign correction has been made before reselling or releasing the vehicle. Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer and arrangements made to make the required correction according to instructions contained in this campaign.

TO104 US/1

**INSTRUCTION TO PERFORM CAMPAIGN #135****Affected Models:**

Certain 2013 through 2016 model year Winnebago® and Itasca® motorhomes.

**Repair Procedure:**

Refer to the instruction sheet for hose assembly replacement.

**Parts Information:**

To minimize any inconvenience to your customers, we strongly encourage you to promptly order part kits for the vehicles on the attached list. This will ensure you have adequate inventory for your customers. Order the following Part Kit from Winnebago Industries® using the WinPortal system. You will be placing the order as a recall order. You will need the recall dealer number and the Winnebago Industries serial number of the affected vehicle to place the order.

- Part Number RC7607-16-735 is for 170X, 170A, 623B, and 623L without drop tube.
- Part Number RC7608-16-735 is for 170X and 170A with drop tube.
- Part Number RC7609-16-735 is for 170C.

| Dealer Number: 7607 |                   |               |
|---------------------|-------------------|---------------|
| Qty.                | Part Description  | Part Number   |
| 1                   | Instruction Sheet | RC7607-16-735 |
| 1                   | Hose              |               |

| Dealer Number: 7608 |                   |               |
|---------------------|-------------------|---------------|
| Qty.                | Part Description  | Part Number   |
| 1                   | Instruction Sheet | RC7608-16-735 |
| 2                   | Hoses             |               |

| Dealer Number: 7609 |                   |               |
|---------------------|-------------------|---------------|
| Qty.                | Part Description  | Part Number   |
| 1                   | Instruction Sheet | RC7609-16-735 |
| 2                   | Hoses             |               |

**REIMBURSEMENT**

When the service has been completed, submit the labor amount and labor operation number listed below. Your repair order must be properly signed by both the dealer and the owner.

|                              | OPERATION<br>NUMBER<br>Dealer No.: 7607 | OPERATION<br>NUMBER<br>Dealer No.: 7608 | OPERATION<br>NUMBER<br>Dealer No.: 7609 |
|------------------------------|---|---|---|
| REPLACEMENT OF<br>LP HOSE(S) | 24350101                                | 24350201                                | 24350301                                |
| TIME ALLOWANCE               | 0.5 hr.                                 | 0.7 hr.                                 | 0.7 hr.                                 |

Thank you for your cooperation.

---

Winnebago Industries, Inc.  
Forest City, Iowa 50436

TO104 US/2

Enclosures